


Forma T

A

A	B	Espesor
15	10	1.3
15	15	1.5
15	15	2
20	11.3	1.3
20	13	1
20	20	1
20	20	1.1
20	20	1.2
20	20	1.3
20	20	1.45
20	20	1.5
20	20	2
20	30	1.2
20	40	2
20	40	4
21.2	13.5	1.2
24	24	1.35
25	25	1
25	25	1.3
25	25	1.5
25	25	2
25.4	25.4	1
30	15	2
30	20	3
30	30	1.3
30	30	1.4
30	30	1.5

A	B	Espesor
30	30	2
35	35	1.5
35	35	2
40	20	2
40	25	1.2
40	35	3
40	40	1.3
40	40	1.4
40	40	1.5
40	40	1.6
40	40	2
40	40	3
40	40	4
40	60	5
45	25	5
50	22	2
50	35	3
50	50	2
50	50	5
50	70	2
55	55	5
58	18	10
60	20	2
60	60	1.3
60	60	1.5
60	60	3
60	60	4



Forma T

A

A	B	Espesor
60	60	7
62	40	3
70	52	2
70	70	1.5
70	70	2
70	70	4
72.5	37.5	2.5
80	26.5	1.5
80	45	2
80	60	2.5
80	60	8
80	66	4.5
80	80	6.4
80	100	20
93	48	3
94	61.7	1.8

A	B	Espesor
100	50	2
100	52	2
100	60	2
100	60	201
100	60	4
100	60	5
100	70	4
100	100	10
102	32.5	9.5
104	80	6.8
110	100	2.5
110	45	2
120	50	2
130	67	6